



**DESCRIPTION**

Ensure main supply is turned off

- A. Rough in cables - hole no larger than 15mm in diameter.
- B. Fit mounting bracket onto the mounting surface with self-tapping screws.
- C. Slide seal on around backing plate, ensuring there is no folding or twisting in the silicone.
- D. Connect main supply wires making sure all connections are tight. Slide on the main body of the Orb Ledge.
- E. Whilst pushing against seal, tighten the screws on the side of the fitting.
- F. Connect G9 lamp, place seal, and twist on Orb Glass (do not over tighten).

