
ORB MAX



DESCRIPTION

- 1. Ensure mains are switched off.
- 2. Connect electrical cables with connector box provided at ceiling canopy (1)
- 3. Fix ceiling canopy (1) to ceiling with screws provided.
- 4. Install the light source* to lamp holder (3)
- 5. Twist the glass (4) to the lampholder cap (2)

*Lamps excluded

